

Multi-Parameter Outfits

Digital Outfit ColorQ DW



Digital Outfit ColorQ DW**

ColorQ DW Code 2059-01 • Shipping Code (weight/lbs.): R1 [4]
Reagent Refill • R-2059-01 • Shipping Code (weight/lbs.): R1 [2]

	Hardness	pH	Iron	Nitrate	Chlorine Free & Total	Sulfide
Range	1-41 gpg*	5-9	0-3.0 ppm*	0-25	0-10 ppm	0-3.0 ppm*
Resolution	1 gpg	0.5 pH	0.5 ppm	1 ppm	0.2 ppm	0.2 ppm
Number of Tests	140	70	50	50	50	120

*Higher Concentrations by dilution; instructions included. **⚠️ WARNING: Cancer - www.P65Warnings.ca.gov

Visual Kits

Model AR outfits offer the simplest, most economical way to measure water quality factors in the field. Drop Count and Octa-Slide tests can be reliably performed by non-technical personnel. Ideal for service applications. Units easily customized upon request.

Need guidance on product selection?
Contact our technical support staff
at 800-344-3100 or
tech@lamotte.com



Visual Kits**

Code 4783-03 • Shipping Code (weight/lbs.): R1 [7]
Reagent Refill • R-4783-02

Popular AR-02 outfit provides tests for Hardness, Iron, and pH. Drop Count test for Hardness (10 ppm or 1 gpg/drop). Octa-Slide tests for Iron (0.5-10 ppm) and pH (5.0-10). Includes 100 tests for Iron and 50 tests each for pH and Hardness.

**⚠️ WARNING: Reproductive Harm - www.P65Warnings.ca.gov

Code 3590-03 • Shipping Code (weight/lbs.): R1 [7]
Reagent Refill • R-3590-01

The Model AR-42 has the same test range for pH, Hardness, and Iron as the AR-02, but it also is equipped to test for Sulfide (0.2-20 ppm). Includes 50 tests for pH, Hardness, and Sulfide; 100 for Iron.

**⚠️ WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov

Ship Codes: [NH] Non-Hazardous Material - No Fees • [R1] Small Qty. Hazardous Material - No Fees • [R2, R3, & LQ] Hazardous Material - Air Fees Only • [HF] Hazardous Material - Air & Ground Fees

LaMotte Water Conditioning Testing Products • 800-344-3100 • www.lamotte.com